
\mathbf{D}

 \mathbf{E} \mathbf{A} \mathbf{E} - - \mathbf{F}

Caroline King & Raleigh King
Dalhousie University • Office of Sustainability • 18 June, 2013



O E



The purpose of this report is to identify shower facilities on Dalhousie's Peninsula Campuses which includes Studley, Sexton and Carleton that may be used by those in the Dalhousie Community that use active transport.

ME HOD

For this project, all washroom facilities owned by Dalhousie and located on the Peninsula were visited from June 19, 2012 to September 4, 2012. If a shower was present in the building then the location (building, unit, floor & room number), washroom classification (male, female or both), maintenance requirements, shower type (private, not private or semi-private), and additional notes on recommendation were recorded. Pictures were taken of all shower facilities with exception of those located in buildings that used to be residential. For shower facilities located in

buildings that used to be residential, a verbal account of the shower was received from an individual that works in the building. This was assumed sufficient because these facilities are only accessible to those that work in the building. All residences have showers for those residing there.

FINDING

All Accessible Showers

The following are showers that are identified as accessible to all of the Dalhousie Community.

* Please note- the Dalplex is available to all members of the Dalhousie Community, but requires a purchased membership.

Building	Unit	Floor	Room Number (NEAR)	Male (M)/ Femal	

Building	Unit	Floor	Room Number (NEAR)	Male (M)/ Femal e (F)/ BOTH	Type (Private (Y OR N)/ SEMI)
6; TP9<(#?H@B@I (

Showers that Require Maintenance

The following are showers that were identified as requiring maintenance.

Building	Floor	Room Numb er (NEA R)	Male (M)/Female (F)/BOTH	Type (Private (Y OR N)/ SEMI)
5C00; @(3C?6Q? <s(< td=""><td>3"6%+%O5</td><td>82J)</td><td>+</td><td>Υ</td></s(<>	3"6%+%O5	82J)	+	Υ
Central Services Building	#%' %#()		345/	6%+,

ECOMMENDA ION

Unisex

The following showers should be made unisex.


Building	Floor	Room Number (NEAR)	Male (M)/ Female (F)/ BOTH	Туре

Require Signage


All shower facilities require proper signage it is recommended that signage be put up for all endof-trips facilities with uniform branding. The following showers require better signage immediately.



Sir James Dunn Level B



Killam Library Level B Female



Killam Library Level B Male



Student Union Building Level 3



Tupper Building Basement




Sexton Library Building Complex Women's Locker Room



Murray Building




LSC Room 1818




LSC Room 1810



LSC Room 2687




Central Services Level 2 Men's Locker Room



Central Services Level 2 Unisex Shower



LSRI Basement



LSRI Basement

ADDI IONAL HO E INFO MA ION

101111	110 L	11 11 0	MILL TOTA		

Showers Only Accessible to those Working in the Building								
3C?6Q? <s(< th=""><th>R<?P(</th><th>*[99@(</th><th>299: (OC: H;@(LO%'' 2M(</th><th>6Z9∖;<i>@</i>(L-</th><th></th><th></th><th></th></th></s(<>	R P(</th <th>*[99@(</th> <th>299: (OC: H;@(LO%'' 2M(</th> <th>6Z9∖;<i>@</i>(L-</th> <th></th> <th></th> <th></th>	*[99@(299: (OC: H;@(LO%'' 2M(6Z9∖; <i>@</i> (L-				

